





FlowBin

Mounting instruction

Mount crossbar into uprights




2 Push down to ensure that crossbar is securely fixed




© HL Display 2(12)

3 Place the metal bin on the crossbar




4 Pull up front




© HL Display 3(12)

5 Loosen wing nuts




6 Insert hydraulic block




© HL Display 4(12)

5 Tighten wing nuts




6 Re-attach front




© HL Display 5(12)

FlowBin – Insert the box

Prepare the box




2 Insert the box




© HL Display 6(12)

FlowBin - Insert the box

3 Attach MAXIFLOW to connector tube




4 Open MAXIFLOW




© HL Display 7(12)

FlowBin – Insert the box

5 Re-attach front




6 Push down front




© HL Display 8(12)

FlowBin – Remove the box

Pull up the front and hang it on the bottom hook




2 Close the MAXIFLOW




© HL Display 9(12)

FlowBin – Remove the box

Release MAXIFLOW from connector




4



© HL Display 10(12)

FlowBin – Remove the box


5 Remove the box




© HL Display 11(12)

FlowBin – Sign holder

Mounting sign holder




2




© HL Display 12(12)

FlowBin - ESL

Mounting ESL



2



© HL Display 13(12)

